

RECEIVING INSPECTION REPORT
 Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080096-8 127861

RECEIVED FROM

Paul B. later Company

DATE REC'D 12-21-56

P. O. NO. 4941

VENDOR PACKING SLIP NO. 16480

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W. O. NO.
322		NOTED		0	3	00	00	02	

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
12	Spring Plunger Valve 219-30 731302-15 (000000-1015)	12		

RECEIVED BY

Jordan

INSPECTED BY

DWA

DATE 1/3/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT
 HYCON MFG. COMPANY
 2961 E. COLORADO ST., PASADENA 8, CALIF.

No 127852

RECEIVED FROM

Woods Aircraft Supply Co.

DATE REC'D 19-DEC-56

P. O. NO. 49108 9421

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	ACCT. OR W. O. NO.
		NOTED							

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY		REMARKS
		ACCEPTED	REJECTED	
10	Relay DPDT 28VDC 10A Contacts AN 3107-1 730125-6 (382-000000-10163-0-0-00-00-02)	10		

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080096-8

INSPECTED

DWA

DATE

1/4/56

REJECTS RETURNED ON SHIP. MEMO NO.